

PHENIX WEEKLY PLANNING





5/14/2009 Don Lynch



Yesterday's Maintenance Access Day

- RPC Installation Crane Measurements
- RPC Installation Support measurements
- MuTrigger FEE South Cable Tray planning
- · RPC3 N gap interferences planning
- HBD Troubleshooting
- Other Work?

Next Maintenance Access Day - May 27

Anyone wishing to access the Tunnel either north or south of the IR should inform the RC at least 2 days ahead of time to coordinate with C-A-D. If you require technician assistance inform me as well.





Upper Support
Brackets
needed here.


Brackets to have up-down and east west adjustments



And here

05/14/2009







Steps

Platform

Need to design and fabricate easier access (steps and platform) for work above MuID steel.



Shutdown '09 Major tasks (expect 5 month shutdown):

- EOR party June 26/2009 shutdown Begins June 28
- End run, remove wall, MuID collars down, EC to AH (3 weeks)
- RPC Factory Operations (in progress and continuing beyond Shutdown '09)
- · RPC Station 3 North (entire shutdown)
- Install Station 1 South scaffolding (1 week)
- Install Station 2/3 scaffolding (2 weeks)
- Install stations 1, 2 and 3 south MuTrigger FEE's (12 weeks)
- MuTr decapacitations: station 3 south (3 weeks)
- · PC1 East repair (4 weeks)
- Mechanical/Electrical Plumbing installation of (4) new DCM racks
- · Add Ar Dewar and expand gas pad to add storage (12 weeks)
- · Prep for future upgrades/existing equipment maintenance & Repair (as necessary)





Shutdown Prep Now to June 28

Task	Complete By
RPC Installation design parts & Tools	May 15
RPC Electronics Rack Prep	June 20
RPC Installation parts and Tools Fabrication	June 28
MuTrigger FEE Parts and Tools ordering	June 28
MuTrigger FEE Cable Management plan	June 15
RPC3 N Cable and Piping relocation Plan	June 15
RPC Factory Tools complete and commissioned	June 28



End of Run, Start of Shutdown

•	Ta	sk	Completion	Date
	•	End of Run Party		6/26
	•	End of Run 9		6/28
	•	Flammable Gas Purge		6/30
	•	Open Wall and Disassemble		7/2
	•	MuID Collar Removal		7/8
) 	•	Move MMS South		7/10
	•	Test RMC Higher comm speed on EC before disconnecting		7/15
	•	Disconnect EC and move to AH		7/17
•	•	Move MuID Collars to AH		7/20
	•	Install IR floor plates, rolling cart & manlift in IR		7/22
	•	Reconnect EC for shutdown mode		7/24
	•	Remove East/West vertical & Upper Bias MMS lampshades	s	7/24
0	5/14/	2009		




RPC Factory Operations

•	Gap and Module assembly and testing (continues through shutdown)	in-progress
•	Gap and Module Storage with humidity control (need to get permanent elec., 2 nd humidity controller & covers for last 3 storage racks)	Nearly complete
•	Tilting transport Table	Nearly complete
•	Burn in test stand (Bike rack section)	In Progress
•	Burn-in test stand gas system and controls (ready for 1st half octant)	5/29
•	Assembly of half-octants for station 3 north	6/1-9/1

RPC Factory












PH EN

RPC Factory Burn In Test Station For Octant and Half Octant Burn-in Tests





Assembly to begin soon








RPC3 North Installation Schedule

Task	Completion Date
Installation Concept Finalized Half-Octant Brackets, Connecting Blocks, under	Apr. 24
detector translating support design	Apr. 30
Installation Fixturing and Tooling Design	May 15
Redesign crystal palace/IR Gas Barrier	May 29
End of Run 9	June 28
Fixturing/Tooling, Brackets/Block/support Fabrication	June 30
Move Shielding/Remove Crystal Palace	June 29-July31
Move cable trays and piping in gap 5	June 29-July 31
Simulated (practice) installation with new fixturing/	·
tooling	July 13-July 31
Install, level & survey support structure	Aug. 3 - Aug 14
Half Octant Testing and Assembly Complete	Aug. 17- Sep. 18
(1st half Octant ready by Aug. 17, 16th by Sep. 18)	
Mechanical Install Align & survey RPC3 N	Aug 17 - Sep. 30
Install 3 elect. Racks, all cables & gas system	Oct. 1 - Oct. 30
Commissioning	Nov. 1 - Nov. 30
Install new crystal palace/IR Gas Barrier & Shielding	Nov. 1 - Nov. 30
Start Run 10	Dec. 1

After the base support structures have been installed, Install the unistrut guide rails at the pedestal and at beam height levels and $+/-\sim 6$ ft from beam height on east and west tunnel walls as shown. These rails will be used to prevent pitch rotation (about the horizontal axis perpendicular to the beamline [X-axis]). In addition there will be 4 sets of adjustable brackets above the MuID Steel adjacent to gap 5 and corresponding to the upper bracket ears on Half-octants HO_8 east and HO_8 west.

S Above gap 5 steel

West @ beam height & +/- 6 ft from Beam height



East @ beam height & +/- 6 ft from Beam height


Note: This view looks thru MuID Steel which has been made transparent for this representation

Along top of pedestal



After HO1 west is installed, the clamp shown is used to keep the HO stable in the vertical configuration. Clamp is idealized actual clamp will have

adjustments to align the pitch angle.




Unistrut low profile rail

Clamp


Note: These views look thru MuID Steel which has been made transparent for this representation

TECHZICAL SUPPO RT 20 0





HO_3 attached to vertical unistrut guide rail here




View angle reversed for clarity




05/14/2009


Half Octant West #4




Sliding clamp

PH**※**ENIX










View looking thru Muld steel plates which have been made transparent. After HO_1 is positioned onto HO_3, inner angled connector at inner 3.4 joint is bolted, inner straight connector has been unbolted from lifting fixture and remains in place to accept HO_5. At ourser face lower brackets have been locked into angled bracket at outer 3-4 joint and straight bracket remains in place to accept HO_5. West sliding base is slid west 60" and clamp is attached to the outer face of HO_4 and positioned to slide in the mid plane unistrut channel. After the clamp is attached lide the base back to the O position













View looking thru MuID steel plates which have been made transparent. After HO_4 is positioned onto HO_3, inner angled connector at inner 3-4 joint is bolted, inner straight connector has been unbolted from lifting fixture and remains in place to accept HO_5. At outer face lower brackets have been locked into angled bracket at outer 3-4 joint and straight bracket remains in place to accept HO_5. West sliding base is slid west 60" and outer mounting bracket is attached to vertical unistrut guide After the bracket is attached, slide the base back to the 0 position





Half Octant West #8


TECHZICAL SUPPORT 2009




























05/14/2009




Half Octants HO_1 East through HO_4 East are installed similarly to their wester counterparts.





HO_8 East and HO_7 East are installed similarly to their western counterparts.








MuTrigger FEE South

	Task	Completion Date
•	Install Station 1 South Scaffold (carpenter	s) 7/31
•	Install Station 1 cable management	8/14
•	Install station 2/3 scaffolding (Techs)	8/14
•	Install station 1 FEE's & Electronics	8/28
•	Install station 2 & 3 cable mngment	8/28
•	Station 1 plumbing	9/11
•	Install station 2/3 FEE's & electronics	9/25
•	Station 2/3 plumbing	10/9



Concept approved at C-A Design Review

Met with Donna Dowling to discuss Bargaining Unit negotiations

MMS scaffolding

Designed for MuTr installation. Approved in 2000 for use. Stress analysis done for worst case. Current design has minor modifications.







MuTr Decapacitations

Task

Station 2/3 Decaps

Testing/verification

Completion Date

8/14-8/28

9/4

TECHZICAL SUPPORT 2


PC1 East Repair PHENIX Completion Date Task Design Repair support fixture Done Review and approval Done **Fabrication** 7/1 (order placed) Install support fixture 8/14 Remove cables and plumbing 8/28 Roll out DC/PC1 9/4 9/11 Replace failed PC1 Roll DC/PC1 in 9/18 Restore cables and plumbing 9/25 0 9 10/2 Test/commissioning

UPP

PC1 East Repair Fixturing Design

Repairs to be performed during '09 Shutdown


Access to PC1 is adequate to remove and replace module



Quote Rec'd from **CS**

New Column Supports Under railway extensions New Railway extensions will allow DC to be pulled out ~ 3 feet more


05/14/2009



	Task	Completion Date
•	Proposal	Done
•	Review and Approval	5/1
•	Design	6/1
•	Site Preparation	7/1
•	Install Empties racks	8/1
•	Install Ar Dewar	9/1
•	Test and Commission	10/1
	(Rough guess actual schedule TBD)	



New Argon Dewar



New storage pad for empty gas cylinders, 20'x 20', 9" min thick. reinforced concrete

New Argon Dewar Pad, 16' x 20', 12" minimum thickness, reinforced concrete.

Met with Dave Phillips to walk thru the plan

New DCM Rack Plumbing

(Not Scheduled Yet)



4 new DCM racks need cooling water plumbing


Other Work

Upgrades Support:

New Beampipe sections (non-Be)
(Sent Drawings to Mike Mapes)
New Beampipe supports
FOCAL prototype design support
VTX fabrication tooling design
VTX installation design
FVTX design/eng'g support

Summer Sunday Prep
TBD Existing Detector Maint & Repairs
Maintenance & Overhead Tasks
Rack Room Reorganization








C-A-D AC, Water System, Electrical system work which may impact shutdown schedule: Tasks, schedules, priorities TBD



2009 Building Maintenance Issues

- Roof leaks in utility bathroom at northwest corner behind tech offices and over door between rack room and assembly hall.
- Heat wrap tape for trailer bathroom toilet drains to prevent freeze/clogging in winter.









Safety, Security, etc.

PHENIX Safety Goals for this years shutdown:


5. Injuries avoided due to good planning - All

Safety is everyone's responsibility. We plan so we stay safe.



Where To Find PHENIX Engineering Info

Its going to be a busy summer, so get on board with your work requests now.



Links for the weekly planning meeting slides, archives of past meeting slides, long term planning, pictures, videos and other technical info can be found on the PHENIX Engineering web site:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm